

SITE INSPECTION REVIEW FORM

SITE NAME: Monroe Township Wells 4+5
ALIASES: _____
SITE I.D.#: NJD 9807 69 699

<u>ITEM</u>	<u>COMPLETE</u> <u>YES</u>	<u>?</u> <u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<u>✓</u>	_____
SITE BACKGROUND	<u>✓</u>	_____
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<u>✓</u>	_____
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<u>✓</u>	_____
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<u>✓</u>	_____
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<u>✓</u>	_____
POTENTIAL FOR DIRECT CONTACT	<u>✓</u>	_____
CONCLUSIONS + RECOMMENDATIONS	<u>✓</u>	_____
REFERENCES	<u>✓</u>	_____

HRS PRE-SCORE: PRELIMINARY SCORE = 42.23
PROJECTED SCORE = 42.23



COMMENTS:

LST is recommended since
groundwater contamination has already been
confirmed

REVIEWED BY:

J. Paul

DATE:

12-19-83

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS